

## Cook, Thomas

---

**From:** Christiansen.Jim@epamail.epa.gov  
**Sent:** Friday, January 07, 2005 7:41 AM  
**To:** Cook, Thomas  
**Subject:** Re: Flyway Figures

**SDMS Document ID**



**2030757**

**Attachments:** Flyway - FenceWork.pdf; Flyway - A1May02\_FenceWork.pdf; Flyway - A2-1\_FenceWork.pdf



Flyway -



Flyway -



Flyway -

nceWork.pdf (811 Klay02\_FenceWork.p1\_FenceWork.pdf (

Looks fine. Have 3 color copies printed for me in Libby and given to Linda to hold for me if you could.

"Cook, Thomas"	To:	Jim
<CookTE@cdm.com>		
Christiansen/EPR/R8/USEPA/US@EPA	cc:	
01/06/2005 12:55	Subject:	Flyway Figures
PM		

Jim,  
Please review and let me know if you have any comments.  
Thanks,  
Tommy

---

Thomas E. Cook  
CDM | consulting· engineering· construction· operations  
1331 seventeenth street, suite 1100  
denver, colorado 80202  
phone: 720.264.1117  
fax: 303.295.1895  
cookte@cdm.com

(See attached file: Flyway - FenceWork.pdf) (See attached file: Flyway - A1May02\_FenceWork.pdf) (See attached file: Flyway - A2-1\_FenceWork.pdf)

# Color Map(s)

The following pages  
contain color that does  
not appear in the  
scanned images.

To view the actual images, please  
contact the Superfund Records  
Center at (303) 312-6473.

# Libby, Montana

## KDC Flyway Property Pre-Removal Soil Results And Sampling Grids

Asbestos Levels  
In Soil (by PLM)

### Surface Samples

- No Data
- ND
- <1%
- 1%
- 2%
- 3%
- 4%
- ≥5%



### Depth Samples

- No Data
- ND
- <1%
- 1%
- 2%
- 3%
- 4%
- ≥5%

Approximate Flyway  
Property Boundary

100 FT Grid Tile

Grids Requiring Removal


Clean Grids

Cleaned Grids Containing  
Areas of Excavation

# CDM



200 0 200 Feet



# Libby, Montana KDC Flyway Property

Soil Sampling Results (Investigative  
& Removal Area)

Asbestos Levels  
In Soil (by PLM)

## Surface Samples

- No Data
- ND
- <1%
- 1%
- 2%
- 3%
- 4%
- ≥5%

## Depth Samples

- No Data
- ND
- <1%
- 1%
- 2%
- 3%
- 4%
- ≥5%

Approximate Flyway  
Property Boundary

100 FT Grid Tile

2002 Removal Areas

Map Projection UTM Zone 11 NAD83 FT

**CDM**



150 0 150 Feet





## Libby, Montana


**Figure A2-1**


## KDC Flyway Property 2001 Removal Results and Clean Sampling Grids

### Asbestos Levels In Soil (by PLM)


### Surface Samples

- No Data
- ND
- <1%
- 1%
- 2%
- 3%
- 4%
- >5%

 Approximate Flyway  
Property Boundary

 100 FT Grid Tile

### Clean Grids

 Cleaned Grids Containing Areas of Excavation



# CDM



200                      0                      200 Feet



Approximate Location of  
Grace Fence Work

River Runs Through It CSS:

1. No visible vermiculite
2. All analytical results are nondetect